## Oil Field Environmental Incident Summary

**Responsible Party:** CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: MARSHALL 1-13H

Field Name: LITTLE KNIFE Well File #: 20256

Date Incident:4/25/2016Time Incident:10:00Facility ID Number:County:DUNNTwp:145Rng:97Sec:13Qtr:

Location Description:

Submitted By: Todd Senescall Received By:

Contact Person: Ben Lemieux

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

12 Barrels 11.5 Barrels 12 barrels

Brine Other

Oil

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 5/19/2016 Clean Up Concluded: 5/10/2016

Risk Evaluation:

fire

Areal Extent:

## Potential Environmental Impacts:

location soil

## Action Taken or Planned:

Treater drained down. Standing fluid sucked up with a trash pump and absorbent pads. Contaminated soil will be recovered when ground conditions dry out. Ball and seat replaced.

Wastes Disposal Location: liquid - swd

soil - R360

Agencies Involved: Doug Dolyniuk - NDIC inspector

**Updates** 

Date: 4/25/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

According to the report, the release was contained to the well pad. NDIC retains oversight.

Date: 6/6/2016 Status: Correspondence Author: Suess, Bill

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Bill Suess sent a No Further Action letter dated June 6, 2016.